



AUDI A5: 1EMU037			
Vinnnumber:	<b>WAUZZZ8TXDA044892</b>	Versionname:	<b>A5 SB DPF Multitr. 136PK Aut.</b>
First Registrationdate:	<b>25/01/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>169792</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3228</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

Options			
Radio CD		Central consol F	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>Tow bar removable</b>
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		
Sport seats			

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

Degree of wear				
	<b>225/50/17/98 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Continental: 7 mm</b>	Re.R.	<b>Continental: 7 mm</b>

Assistance equipment	
Spare tyre compact	<b>Yes</b>

Total cost ex VAT	1351,32
Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

Protection plate M, Tear, E - Replace	74,00
---------------------------------------	-------



Door R L, Bump(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bonnet, Stone chip(s), LI - Repair and paint (complete)	254,16
---	--------



Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Wing R R, Scratch(es), LI - Repair and paint (complete)	369,84
---	--------



Interior, Dirty, Cleaning	50,00
---------------------------	-------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Wing F R, Bump(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display