



AUDI A1: 1GAZ384

Vinnumber:	WAUZZZ8X8EB027099	Versionname:	A1 5B Attraction 90PK
First Registrationdate:	11/12/2013	Fiscalpower:	
Expertise Mileage:	106943	Power Kw:	66
Bodytype:		Body color	Brown
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3208
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	195/60/16/88 T LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Semperit: 6 mm	Re.R.	Semperit: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1213,94
--------------------------	----------------

Interior, Dirty, Cleaning	100,00
----------------------------------	---------------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
---	--------------



Wing R L, Scratch(es), LI - Repair and paint (complete) 246,56



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F R, Scratch(es), LI - Repair and paint (complete) 176,14



Wing R R, Scratch(es), LI - Repair and paint (complete) 246,56



Door R R, Scratch(es), LI - Repair and paint (complete) 254,68

