



CITRO?N C4 Picasso: 1FKT709

Vinnnumber:	VF7UA9HR8DJ679443	Versionname:	GR.C4 PICASSO
First Registrationdate:	31/07/2013	Fiscalpower:	7pl.Seduct.FAP 112PK
Expertise Mileage:	119630	Power Kw:	82
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2309
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	215/55/16/93 V LightMetal			
Summer tyres:	Fr.L.	Vredestein: 3 mm	Fr.R.	Vredestein: 3 mm
	Re.L.	Vredestein: 3 mm	Re.R.	Vredestein: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	952,04
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00



Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Bump(s), PDR - Knock out without painting	63,00



Rocker panel inner R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 115,56



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Ignition key, Missing, P - Check 0,00

No pictures to display

Wing R R, Bump(s), Acceptable 0,00

No pictures to display

Door R R, Bump(s), Acceptable 0,00

No pictures to display

Rocker panel inner R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 115,56



Interior, Dirty, Cleaning 25,00



Wing R R, Bump(s) and scratch(es), It - Spot repair 115,56



Wing R L, Bump(s), Acceptable 0,00

No pictures to display

Rocker panel inner F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 115,56



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80





Tailgate, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Seat cover F L, Worn, P - Check	0,00
---------------------------------	------



Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display