


**BMW X1: 1GIE452**

|                                    |                          |              |                               |
|------------------------------------|--------------------------|--------------|-------------------------------|
| Vinnumber:                         | <b>WBAVY11040VZ66239</b> | Versionname: | <b>X1 sDrive16 116PK Aut.</b> |
| First Registrationdate:            | <b>14/02/2014</b>        | Fiscalpower: |                               |
| Expertise Mileage:                 | <b>119067</b>            | Power Kw:    | <b>85</b>                     |
| Bodytype:                          |                          | Body color:  | <b>Orange</b>                 |
| Gearbox:                           | <b>Automatic</b>         | Paint type:  | <b>Metalic</b>                |
| Transmission:                      | <b>Back</b>              | Rims summer: | <b>Aluminium</b>              |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                     |
| Maintenance:                       | <b>IN 13000 KM</b>       | Parking lot: | <b>2232</b>                   |
| Maintenance:                       | <b>OK</b>                |              |                               |
| Battery functioning:               | <b>Yes</b>               |              |                               |
| Number of doors:                   | <b>5</b>                 |              |                               |
| Number of seats:                   | <b>5</b>                 |              |                               |
| Number head rests:                 | <b>5</b>                 |              |                               |
| Rims summer:                       | <b>Aluminium</b>         |              |                               |
| Category:                          | <b>Passenger Car</b>     |              |                               |
| Oil level:                         | <b>OK</b>                |              |                               |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                               |

**Options**

|                                |                              |                       |
|--------------------------------|------------------------------|-----------------------|
| Radio CD                       |                              | Central consol F      |
| GPS storage                    | <b>HD</b>                    | Luggage cover         |
| GPS storage                    |                              | Front parking sensors |
| Windows electric F             |                              | Rear parking sensors  |
| Windows electric R             |                              |                       |
| Cruise Control                 |                              |                       |
| Steering wheel multifunctional |                              |                       |
| Radio multimedia               |                              |                       |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                       |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |
| Type of Lining                 | <b>Lining semi-leather</b>   |                       |
| Type of climate control        | <b>Autom climate control</b> |                       |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Idle position       | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Lighting            | <b>OK</b>  |
| Transmission        | <b>OK</b> | Wiperblades         | <b>OK</b>  |
| Handbrake           | <b>OK</b> |                     |            |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>225/45/18/91 V LightMetal</b> |                       |       |                       |
| Summer tyres: | Fr.L.                            | <b>Goodyear: 5 mm</b> | Fr.R. | <b>Goodyear: 5 mm</b> |
|               | Re.L.                            | <b>Goodyear: 6 mm</b> | Re.R. | <b>Goodyear: 6 mm</b> |

**Assistance equipment**

Runflat **Yes**

|  |         |
|--|---------|
| Total cost ex VAT  | 1623,24 |
| Alloy rim R L, Scratch(es), LI - Repair and paint (complete) | 95,00   |



|  |       |
|--|-------|
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 246,56



Bumper R, Crack, Le - Replace and paint 651,00



Wing trim R R, Scratch(es), E - Replace 72,00



Rearlight R , Damaged, E - Replace 114,00



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,68



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

