


BMW 3: 1HJV826

Vinnnumber:	WBA3K910X0F912199	Versionname:	3 TOURING 316dA 116PK Aut.
First Registrationdate:	5/08/2014	Fiscalpower:	
Expertise Mileage:	169966	Power Kw:	85
Bodytype:		Body color	Black
Gearbox:	Automatic	Paint type	Metallic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3733
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Sun Roof electric
GPS storage	HD	Central consol F
GPS storage		Luggage cover
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining artificial leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 4845,74

Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 235,80

Bonnet, Bump(s), PDR - Knock out without painting
63,00



Roof, Scratch(es), Acceptable 0,00

No pictures to display

Door panel F R, Damaged, E - Replace 114,00



Seat cover R R, Burned, E - Replace 360,00



Bumper grille F R, Broken, E - Replace 64,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Seat cover F L, Damaged, Acceptable 0,00



Wing F L, Bump(s), Acceptable 0,00

No pictures to display

Inner door handle R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Backrest cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Bump(s), PDR - Knock out without painting 82,80





Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Front bumper, Bump(s) and scratch(es), E - Replace 499,20



Door F R, Bump(s) and scratch(es), Le - Replace and paint 1082,52



Wing F R, Bump(s) and scratch(es), Le - Replace and paint 530,02



Interior, Dirty, Acceptable 0,00

No pictures to display

Door F L, Scratch(es), LI - Repair and paint (complete) 318,35





Inner door handle R L, Scratch(es), Acceptable 0,00

No pictures to display

Dashboard, Scratch(es), E - Replace 148,00



Spoiler F L, Broken, E - Replace 62,00



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Bumper grille F L, Broken, E - Replace 64,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete) 310,50

