


BMW 3: 1JGP500

Vinnumber:	WBA3K11000F836896	Versionname:	3 TOURING 318d 136PK
First Registrationdate:	12/12/2014	Fiscalpower:	
Expertise Mileage:	164359	Power Kw:	100
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3723
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/60/16/96 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	0,00
-------------------	------

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bonnet, Bump(s), Acceptable	0,00
-----------------------------	------

No pictures to display

Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bumper F L, Scratch(es), Acceptable	0,00
-------------------------------------	------

No pictures to display

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

No pictures to display

Wing R R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display