




| AUDI A6: 1GDM430                   |                          |              |                       |
|------------------------------------|--------------------------|--------------|-----------------------|
| Vinnumber:                         | <b>WAUZZZ4G4EN099616</b> | Versionname: | <b>A6 AVANT 136PK</b> |
| First Registrationdate:            | <b>8/01/2014</b>         | Fiscalpower: |                       |
| Expertise Mileage:                 | <b>165009</b>            | Power Kw:    | <b>100</b>            |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Dark Grey</b>      |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>        |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>      |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>             |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>3608</b>           |
| Number of doors:                   | <b>5</b>                 |              |                       |
| Number of seats:                   | <b>5</b>                 |              |                       |
| Number head rests:                 | <b>5</b>                 |              |                       |
| Rims summer:                       | <b>Aluminium</b>         |              |                       |
| Category:                          | <b>Passenger Car</b>     |              |                       |
| Oil level:                         | <b>OK</b>                |              |                       |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                       |

| Options                        |                              |                       |                      |
|--------------------------------|------------------------------|-----------------------|----------------------|
| Radio CD                       |                              | Central consol F      |                      |
| Windows electric F             |                              | Luggage cover         |                      |
| Windows electric R             |                              | Front parking sensors |                      |
| Cruise Control                 |                              | Rear parking sensors  |                      |
| Steering wheel multifunctional |                              | Type of Tow bar       | <b>Tow bar fixed</b> |
| Seats F heated                 |                              |                       |                      |
| Radio multimedia               |                              |                       |                      |
| Type of headlighting           | <b>Headlighting Xenon</b>    |                       |                      |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |                      |
| Type of Lining                 | <b>Lining leather</b>        |                       |                      |
| Type of climate control        | <b>Autom climate control</b> |                       |                      |

| Limited Technical Inspection |           |                     |            |
|------------------------------|-----------|---------------------|------------|
| Airco functioning            | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile           | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Idle position                | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Engine startingtime          | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Exhaust gass                 | <b>OK</b> | Lighting            | <b>OK</b>  |
| Transmission                 | <b>OK</b> | Wiperblades         | <b>OK</b>  |
| Handbrake                    | <b>OK</b> |                     |            |

| Degree of wear |                                   |                     |       |                     |
|----------------|-----------------------------------|---------------------|-------|---------------------|
|                | <b>225/55/17/101 V LightMetal</b> |                     |       |                     |
| Winter tyres:  | Fr.L.                             | <b>Dunlop: 4 mm</b> | Fr.R. | <b>Dunlop: 4 mm</b> |
|                | Re.L.                             | <b>Dunlop: 5 mm</b> | Re.R. | <b>Dunlop: 5 mm</b> |

| Assistance equipment   |                            |
|--|----------------------------|
| Spare tyre compact   | <b>Yes</b> Jack <b>Yes</b> |
| Total cost ex VAT  | 1175,34                    |
| Wing R R, Scratch(es), Acceptable                            | 0,00                       |
| <i>No pictures to display</i>                                |                            |
| Alloy rim R R, Scratch(es), LI - Repair and paint (complete) | 95,00                      |



|   |        |
|---|--------|
| Front bumper, Scratch(es), LI - Repair and paint (complete) | 254,16 |
|---|--------|



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Scratch(es), LI - Repair and paint (complete) 382,02

