



**BMW 3: 1GXB279**

Vinnnumber:	<b>WBA3E11090P657502</b>	Versionname:	<b>3 BER 320dA Eff.Dynamics Ed.163PK Aut.</b>
First Registrationdate:	<b>23/05/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>151131</b>	Power Kw:	<b>120</b>
Bodytype:	<b>Berline</b>	Body color:	<b>Dark Blue</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1213</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>205/60/16/92 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 6 mm</b>	Fr.R.	<b>Michelin: 6 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

<b>Total cost ex VAT</b>	<b>1848,26</b>
--------------------------	----------------

<b>Bonnet, Chemical polution, LI - Repair and paint (complete)</b>	<b>290,08</b>
--	---------------



<b>Roof pillar R, Bump(s) and scratch(es), LI - Repair and paint (complete)</b>	<b>220,18</b>
---	---------------



<b>Bumper R, Bump(s), Acceptable</b>	<b>0,00</b>
--------------------------------------	-------------

No pictures to display

Door panel R L, Scratch(es), E - Replace 114,00



Full screen GPS, Crack, E - Replace 1224,00



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display