


BMW 316D: 1ENZ242

Vinnumber:	WBA3D91030F404375	Versionname:	3 BER 316d 116PK
First Registrationdate:	4/02/2013	Fiscalpower:	
Expertise Mileage:	110942	Power Kw:	85
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	SERVICE IN 14000KM 3 2018	Parking lot:	2126
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Seats electric F L
Windows electric F	Seats electric F R
Windows electric R	Central consol F
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
Sport seats	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/60/16/92 H Steel			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			438,00
Wheel cover R L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Wheel cover R R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door R R, Bump(s) and scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door R L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Interior, No damage, Acceptable			0,00



Sill trim L, Scratch(es), It - Spot repair

115,56



Front bumper, Scratch(es), LI - Repair and paint (complete)

211,80



Door panel F L, Damaged, Smart repair

110,64

