



MERCEDES CLA: 1FRY997			
Vinnnumber:	<b>WDD1173011N043552</b>	Versionname:	<b>CLA BER 200 CDI 136PK</b>
First Registrationdate:	<b>7/10/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>118985</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3402</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options	
Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Manual climate control</b>

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

Degree of wear				
	<b>225/40/18/92 V LightMetal</b>			
Winter tyres:	Fr.L.	<b>Dunlop: 8 mm</b>	Fr.R.	<b>Dunlop: 8 mm</b>
	Re.L.	<b>Dunlop: 5 mm</b>	Re.R.	<b>Dunlop: 5 mm</b>

Assistance equipment	
Repair kit	<b>Yes</b>
Compressor	<b>Yes</b>

Total cost ex VAT	<b>1708,43</b>
Bumper R, Bump(s), LI - Repair and paint (complete)	<b>211,80</b>



Bonnet, Chemical polution, LI - Repair and paint (complete)	<b>290,08</b>
---	---------------



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35




Ignition key, Missing, E - Replace 150,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Boot carpet, Dirty, Cleaning 50,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00

