


FORD FOCUS CLIPPER: 1EOA382

Vinnnumber:	WF0LXXGCBLDJ58204	Versionname:	ECOnetic T.Trend 115PK
First Registrationdate:	4/02/2013	Fiscalpower:	
Expertise Mileage:	117016	Power Kw:	85
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3201
Maintenance:	104433 KM		
Maintenance:	2/08/2017		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage:	SD	Central consol F:	
GPS storage:		Luggage cover:	
Windows electric F:		Rear parking sensors:	
Steering wheel multifunctional:		Type of Tow bar:	Tow bar fixed
Radio multimedia:			
Type of headlighting:	Headlighting Halogen		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Manual climate control		
Level control:			

Limited Technical Inspection

Airco functioning:	OK	Battery functioning:	Yes
Tires wear profile:	OK	Sound engine:	OK
Idle position:	OK	Clutch test:	OK
Engine startingtime:	OK	Wiper fluid level:	OK
Exhaust gass:	OK	Lighting:	OK
Transmission:	OK	Wiperblades:	OK
Handbrake:	OK		

Degree of wear

	215/55/16/93 H LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
-------------	------------	-------------	------------

Total cost ex VAT:	110,38
Ceiling, Stain, Acceptable:	0,00
<i>No pictures to display</i>	
Door R R, Bump(s), Acceptable:	0,00
<i>No pictures to display</i>	
Door R L, Scratch(es), 67 - Polish:	55,19



Tailgate, Scratch(es), Acceptable:	0,00
------------------------------------	-------------

No pictures to display

Seat cover R, Stain, Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F R, Stain, Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F L, Stain, Acceptable	0,00
<i>No pictures to display</i>	
Interior, Damaged, Acceptable	0,00



Bonnet, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper corner R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Scratch(es), 67 - Polish	55,19

