



FORD Mondeo: 1FRH773

Vinnumber:	WF0GXXGBBGDG62856	Versionname:	MONDEO CLIP ECONetic Trend Style 115PK
First Registrationdate:	1/10/2013	Fiscalpower:	
Expertise Mileage:	108966	Power Kw:	85
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2701
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

215/55/16/93 H LightMetal				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT 842,44

Door F L, Repaired, P - Check 0,00



Wing R R, Bump(s), LI - Repair and paint (complete) 308,20



Floor covering F L, Burned, Smart repair 64,32



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Floor covering F L, Burned, Smart repair 64,32



Wing F R, Bump(s), Acceptable 0,00

No pictures to display


Floor covering F L, Burned, Smart repair 64,32



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Door R L, Repaired, Acceptable 0,00



Internal Boot Lining R, Scratch(es), Smart repair 110,64



Interior, Dirty, Cleaning 25,00



Wing R R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Trunk lid covering R, Scratch(es), Smart repair	110,64
---	--------

