



LEXUS NX: 1LEB491			
Vinnnumber:	JTJBJRBZ502024172	Versionname:	2.5 300H EXECUTIVE LINE
First Registrationdate:	2/09/2015	Fiscalpower:	4WD AUTO
Expertise Mileage:	74392	Power Kw:	114
Bodytype:	SUV	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Hybrid	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1626
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
GPS storage	HD	Seats electric F L	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
Summer tyres:	225/60/18/100 H LightMetal			
	Fr.L.	Yokohama: 3 mm	Fr.R.	Yokohama: 3 mm
	Re.L.	Yokohama: 5 mm	Re.R.	Yokohama: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1240,60
Door R R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door R L, Scratch(es), LI - Repair and paint (complete)			382,02

Tailgate, Bump(s), Acceptable			0,00
<i>No pictures to display</i>			
Roof, Bump(s), PDR - Knock out without painting			63,00



Front bumper, Broken, E - Replace	298,00
-----------------------------------	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper F R, Scratch(es), It - Spot repair	115,56
---	--------



Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Rearview mirror housing L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete)	382,02
---	--------



Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display