



FORD C-MAX: 1ELJ952			
Vinnumber:	WFOJXXWPBJCT61800	Versionname:	C-MAX Titanium St/St
First Registrationdate:	14/01/2013	Fiscalpower:	95PK
Expertise Mileage:	101681	Power Kw:	70
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1610
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Seats electric F L	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar fixed
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	215/55/16/93 H LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 8 mm	Fr.R.	Uniroyal: 8 mm
	Re.L.	Uniroyal: 8 mm	Re.R.	Uniroyal: 8 mm

Assistance equipment	
Spare tyre compact	Yes

Total cost ex VAT	1383,27
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00




Roof, Hail damage, PDR - Hail	0,00
-------------------------------	------





Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), Acceptable 0,00




Door R L, Scratch(es), Acceptable 0,00

No pictures to display


Luggage space cover, Incomplete, Repair/replace (lump sum) 20,00



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Rear bulkhead lining, Hole, Smart repair 110,64



Roof pillar L, Bump(s), PDR - Knock out without painting 0,00



Door panel F L, Damaged, E - Replace 114,00



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68

