


FORD Smax: 1A1S587

Vinnumber:	WF0SXXGBWS6M50337	Versionname:	
First Registrationdate:	24/11/2006	Fiscalpower:	
Expertise Mileage:	173034	Power Kw:	92
Bodytype:	MPV	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats electric F L	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS base		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	235/45/18/98 W LightMetal			
Summer tyres:	Fr.L.	Other: 5 mm	Fr.R.	Other: 5 mm
	Re.L.	Firestone: 6 mm	Re.R.	Firestone: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	784,85
Bonnet, Bump(s), LI - Repair and paint (complete)	348,09



Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Centre console, Worn, Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Scratch(es), It - Spot repair	115,56



Alloy rim F L polished, Rust, Acceptable	0,00
--	------

No pictures to display

Door R L, Scratch(es), It - Spot repair	115,56
---	--------



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Bumper R, Bump(s) and scratch(es), Smart repair	110,64
---	--------

