



**FORD Transit 260S: 1DOF180**

Vinnnumber:	<b>WF05XXBDF5CC39578</b>	Versionname:	<b>TRANSIT 260S B/F2C SWB</b>
First Registrationdate:	<b>5/07/2012</b>	Fiscalpower:	<b>Silv.DPF(E5)125PK</b>
Expertise Mileage:	<b>9296</b>	Power Kw:	<b>92</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>Dark Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3422</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>6</b>		
Number head rests:	<b>6</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Rear parking sensors
Windows electric F	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>195/70/15/102 R Steel</b>			
Summer tyres:	Fr.L.	<b>Continental: 0 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Continental: 6 mm</b>	Re.R.	<b>Continental: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>781,86</b>
Roof pillar R, Bump(s) and scratch(es), It - Spot repair	<b>115,56</b>



Bumper corner R R, Bump(s) and scratch(es), Smart repair	<b>110,64</b>
--	---------------



Bodywork, Not original part, Acceptable	<b>0,00</b>
---	-------------

*No pictures to display*

Trunk door R R, Bump(s), PDR - Knock out without painting	<b>63,00</b>
---	--------------



Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Sliding door R, Bump(s), LI - Repair and paint (complete) 382,02



Dashboard, Scratch(es), Smart repair 110,64

