



MERCEDES B: 1DPI681			
Vinnumber:	WDD2462001J081352	Versionname:	B 180 CDI BE 109PK
First Registrationdate:	13/07/2012	Fiscalpower:	
Expertise Mileage:	177262	Power Kw:	80
Bodytype:	Hatchback	Body color:	Dark Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2728
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT		274,80	
Bumper R, Scratch(es), Acceptable		0,00	
<i>No pictures to display</i>			
Door R L, Scratch(es), Acceptable		0,00	
<i>No pictures to display</i>			
Door R R, Bump(s), PDR - Knock out without painting		63,00	
<i>No pictures to display</i>			
Front bumper, Scratch(es), LI - Repair and paint (complete)		211,80	



Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	