



| PEUGEOT 5008: 1EJV930 | | | |
|-------------------------|--------------------------|--------------|------------------|
| Vinnumber: | VF30A9HD8CS268794 | Versionname: | 1.6 HDI |
| First Registrationdate: | 2/01/2013 | Fiscalpower: | |
| Expertise Mileage: | 142717 | Power Kw: | 84 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 2508 |
| Maintenance: | OVER 7400 KM | | |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

| Options | |
|--------------------------------|--------------------------------|
| Radio CD | Central consol F |
| GPS storage | Luggage cover |
| GPS storage | HD Rear parking sensors |
| Windows electric F | |
| Windows electric R | |
| Cruise Control | |
| Steering wheel multifunctional | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |

| Limited Technical Inspection | | | |
|------------------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

| Degree of wear | | | | |
|----------------|----------------------------------|-----------------------|-------|-----------------------|
| | 215/55/16/93 H LightMetal | | | |
| Winter tyres: | Fr.L. | Michelin: 7 mm | Fr.R. | Michelin: 7 mm |
| | Re.L. | Michelin: 8 mm | Re.R. | Michelin: 8 mm |

| Assistance equipment | |
|--|----------------------------|
| Spare tyre compact | Yes Jack Yes |
| Total cost ex VAT | 352,53 |
| Alloy rim F L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Repaired, P - Check | 0,00 |



| | |
|--------------------------------------|-------|
| Door frame F L, Damaged, E - Replace | 45,73 |
|--------------------------------------|-------|



| | |
|--|-------|
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|



| | |
|---------------------------|------|
| Roof, Bump(s), Acceptable | 0,00 |
|---------------------------|------|

No pictures to display

| | |
|-----------------------------------|------|
| Door F L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|----------------------------------|------|
| Steering wheel, Worn, Acceptable | 0,00 |
|----------------------------------|------|

No pictures to display

| | |
|---|--------|
| Front bumper, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|--------|



| | |
|-----------------------------------|------|
| Door R L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display