



MERCEDES C: 1H2T805

Vinnnumber:	WDD2050361F112554	Versionname:	C BER 180 BlueTEC 116PK
First Registrationdate:	10/11/2014	Fiscalpower:	
Expertise Mileage:	123660	Power Kw:	85
Bodytype:	Berline	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3527
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	195/65/16/97 H Steel			
Winter tyres:	Fr.L.	Dunlop: 6 mm	Fr.R.	Dunlop: 6 mm
	Re.L.	Dunlop: 7 mm	Re.R.	Dunlop: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1436,71
-------------------	----------------







Rearlight R , Crack, E - Replace	114,00
----------------------------------	---------------



Wheel cover R R, Scratch(es), Acceptable	0,00
--	-------------

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Wheel cover F R, Scratch(es), E - Replace	30,00
	
Wheel cover F L, Scratch(es), E - Replace	30,00
	
Sill outer R, Scratch(es), It - Spot repair	115,56
	
Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20
	
Bumper R, Scratch(es), LI - Repair and paint (complete)	259,80
	
Dashboard, Damaged, E - Replace	49,00
	
Door F R, Scratch(es), LI - Repair and paint (complete)	318,35
