


MERCEDES E 200 XDI: 1FDZ039

Vinnnumber:	WDD2122051A810601	Versionname:	E BRE 200CDI BE
First Registrationdate:	4/06/2013	Fiscalpower:	Start/Stop 136PK
Expertise Mileage:	138440	Power Kw:	100
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	3433
Maintenance	SERVICE B1 IN 2900KM		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Seats electric F L
GPS storage	HD	Seats electric F R
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Type of headlighting	Headlighting LED	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/55/16/99 H LightMetal			
Winter tyres:	Fr.L.	Kleber: 4 mm	Fr.R.	Kleber: 5 mm
	Re.L.	Kleber: 3 mm	Re.R.	Kleber: 5 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT 1085,80

Bumper grille F R, Strained , P - Check 0,00



Wing R L, Chemical polution, P - Check 0,00



Interior, No damage, Acceptable	0,00
---------------------------------	------





Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bonnet, Bump(s), PDR - Knock out without painting	399,60
---	--------



Rearview mirror basis R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bumper trim R, Scratch(es), E - Replace	116,44
---	--------



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Roof pillar L, Repaired, P - Check	0,00
------------------------------------	------



Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------



Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door F L, Bump(s), PDR - Knock out without painting	102,60
---	--------



Door F R, Bump(s), PDR - Knock out without painting

63,00

