



FORD Focus: 1FFB399			
Vinnumber:	<b>WF0LXXGCBLDB56146</b>	Versionname:	<b>FOCUS CLIP. EConetic Trend 88g 105PK</b>
First Registrationdate:	<b>12/06/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>168418</b>	Power Kw:	<b>77</b>
Bodytype:		Body color:	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>GEEN MELDING</b>	Parking lot:	<b>2827</b>
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

Options	
Radio CD	Luggage cover
GPS storage	Rear parking sensors
GPS storage	<b>SD</b>
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

Degree of wear				
	<b>205/55/16/91 H Steel</b>			
Winter tyres:	Fr.L.	<b>Michelin: 3 mm</b>	Fr.R.	<b>Michelin: 3 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

Assistance equipment			
Spare tyre compact	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT	<b>822,20</b>		
Seat cover F R, Dirty, Cleaning	<b>25,00</b>		



Roof pillar L, Bump(s), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Wheel cover R R, Scratch(es), E - Replace	<b>30,00</b>



Bumper R, Bump(s) and scratch(es), E - Replace 415,20



Rearlight L, Broken, E - Replace 114,00



Ignition key, Missing, E - Replace 150,00



Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Worn, Acceptable 0,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Bump(s), PDR - Knock out without painting 63,00



Brand badge R, Worn, Acceptable 0,00

No pictures to display

Seat cover F L, Dirty, Cleaning 25,00



Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Roof pillar R, Bump(s), Acceptable 0,00

No pictures to display

Maintenance, Maintenance, P - Check 0,00



Wing R R, Bump(s), Acceptable

0,00

*No pictures to display*