



PEUGEOT 5008: 1ENP394

Vinnnumber:	VF30A9HD8CS268966	Versionname:	5008 e-HDi Allure FAP BMP 115PK Aut.
First Registrationdate:	31/01/2013	Fiscalpower:	
Expertise Mileage:	98489	Power Kw:	84
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	PLUS 1400 KM	Parking lot:	1532
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Sun Roof electric
GPS storage		Panoramic roof
GPS storage	HD	Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Type of headlighting:	Headlighting Halogen	
Type of GPS:	GPS big screen color	
Type of Lining:	Lining fabrics	
Type of climate control:	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	215/55/16/97 H LightMetal			
Winter tyres:	Fr.L.	Kleber: 3 mm	Fr.R.	Kleber: 3 mm
	Re.L.	Kleber: 6 mm	Re.R.	Kleber: 6 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT	1059,00
Front bumper, Scratch(es), LI - Repair and paint (complete)	259,80





Wing R L, Scratch(es), Acceptable 0,00



Door R L, Repaired, P - Check 0,00



Bumper R, Scratch(es), Acceptable 0,00



Door F R, Scratch(es), Acceptable 0,00



Outer door handle F R, Scratch(es), Acceptable 0,00

No pictures to display

Headlight L, Scratch(es), E - Replace 396,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Door F L, Scratch(es), Acceptable 0,00



Wing F R, Scratch(es), Acceptable 0,00



Door F L, Repaired, P - Check 0,00

