


OPEL Astra: 1EXW913

| | | | |
|-------------------------|--------------------------|--------------|---|
| Vinnnumber: | WOLPD8EWXD8048321 | Versionname: | ASTRA BRE ecoFL Enjoy Active St/St 110PK |
| First Registrationdate: | 17/04/2013 | Fiscalpower: | |
| Expertise Mileage: | 132840 | Power Kw: | 81 |
| Bodytype: | Break | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 4232 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | | |
|--------------------------------|-------------------------------|----------------------|
| Radio CD | Central consol F | |
| Windows electric F | Luggage cover | |
| Cruise Control | Rear parking sensors | |
| Steering wheel multifunctional | Type of Tow bar | Tow bar fixed |
| Radio multimedia | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining fabrics | |
| Type of climate control | Manual climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

Degree of wear

| | | | | |
|---------------|-----------------------------|-----------------------|-------|-----------------------|
| | 225/50/17/98 H Steel | | | |
| Winter tyres: | Fr.L. | Uniroyal: 7 mm | Fr.R. | Uniroyal: 7 mm |
| | Re.L. | Uniroyal: 7 mm | Re.R. | Uniroyal: 7 mm |

Assistance equipment

| | | | |
|--------------------|------------|------|------------|
| Spare tyre compact | Yes | Jack | Yes |
|--------------------|------------|------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 241,80 |
|-------------------|---------------|

| | |
|---|--------------|
| Wheel cover F R, Scratch(es), E - Replace | 30,00 |
|---|--------------|



| | |
|---------------------------------------|-------------|
| Front bumper, Scratch(es), Acceptable | 0,00 |
|---------------------------------------|-------------|

No pictures to display

| | |
|-----------------------------------|-------------|
| Door R L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|-------------|

No pictures to display

| | |
|---|---------------|
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|---------------|

