



<b>OPEL Mokka: 1HLZ945</b>			
Vinnnumber:	<b>W0LJD7EL1EB767970</b>	Versionname:	<b>MOKKA ecoFLEX 4x2 Cosmo 130PK</b>
First Registrationdate:	<b>25/08/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>195950</b>	Power Kw:	<b>96</b>
Bodytype:	<b>SUV</b>	Body color	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>2822</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

<b>Options</b>	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Radio multimedia	
Type of headlighting	<b>Headlighting Xenon</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

<b>Degree of wear</b>				
	<b>215/55/18/95 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Continental: 4 mm</b>	Re.R.	<b>Continental: 4 mm</b>

<b>Assistance equipment</b>			
Spare tyre compact	<b>Yes</b>	Jack	<b>Yes</b>

<b>Total cost ex VAT</b>	<b>1014,10</b>
<b>Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)</b>	<b>318,35</b>



<b>Front bumper, Scratch(es), LI - Repair and paint (complete)</b>	<b>211,80</b>
--	---------------



<b>Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete)</b>	<b>318,35</b>
--	---------------



Bonnet, Bump(s), PDR - Knock out without painting	63,00
---	-------



Seat cover F L, Worn, Acceptable	0,00
----------------------------------	------

*No pictures to display*

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Roof, Bump(s), PDR - Knock out without painting	102,60
---	--------

