



VOLKSWAGEN TIGUAN: 1EPG397

Vinnnumber:	WVGZZ5NZDW591853	Versionname:	TIGUAN Trend&Fun BM Tech.110PK
First Registrationdate:	13/02/2013	Fiscalpower:	
Expertise Mileage:	70491	Power Kw:	81
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3104
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Steering wheel multifunctional		Luggage cover	
Type of headlighting	Headlighting Halogen	Front parking sensors	
Type of GPS	GPS big screen color	Rear parking sensors	
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	215/65/16/98 H LightMetal			
Winter tyres:	Fr.L.	Semperit: 7 mm	Fr.R.	Semperit: 7 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	906,88
-------------------	--------

Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Bonnet, Chemical polution, Acceptable	0,00
---------------------------------------	------

No pictures to display

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Roof pillar R, Bump(s) and scratch(es), LI - Repair and paint (complete)	220,18
--	--------



Door F R, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Interior, Dirty, Cleaning	50,00
---------------------------	-------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display