



VOLVO V70: 1EMF077			
Vinnumber:	YV1BW31A1D1264545	Versionname:	V70 D3 Kinetic St/St 136PK
First Registrationdate:	21/01/2013	Fiscalpower:	
Expertise Mileage:	90498	Power Kw:	100
Bodytype:		Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	UITVOEREN	Parking lot:	3108
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	225/55/16/95 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT		837,08	
Door panel F L, Scratch(es), Acceptable		0,00	



Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------



Door R L, Bump(s) and scratch(es), Acceptable 0,00



Outer door handle F R, Scratch(es), Acceptable 0,00



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 302,16



Maintenance, Maintenance, Execute 0,00



Front bumper, Scratch(es), Acceptable 0,00



Floor covering F L, Burned, Smart repair 64,32



Interior, Dirty, Cleaning 50,00



Sill outer L, Scratch(es), LI - Repair and paint (complete) 372,60

oil outer L, Scratch(es), L - Repair and paint (complete) 0,00



Bumper spoiler F, Strained , E - Replace 48,00



Alloy rim F L, Scratch(es), Acceptable 0,00



Steering wheel, Scratch(es), Acceptable 0,00



Wing R L, Repaired, P - Check 0,00



Alloy rim R L, Scratch(es), Acceptable 0,00



Door F L, Scratch(es), Acceptable 0,00

