



VOLKSWAGEN Passat: 1FXJ698			
Vinnnumber:	WVWZZZ3CZEE080199	Versionname:	PASSAT VAR Comfortline
First Registrationdate:	27/11/2013	Fiscalpower:	136PK
Expertise Mileage:	134435	Power Kw:	100
Bodytype:		Body color:	Beige
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4811
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		


Degree of wear				
	215/55/16/93 W LightMetal			
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm


Assistance equipment	
Spare wheel	Yes

Total cost ex VAT	1823,93
Luggage space cover, Missing, E - Replace	240,00




Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rear window, Scratch(es), E - Replace	370,00





Bonnet, Bump(s), LI - Repair and paint (complete) 290,08



Interior, Dirty, Cleaning 50,00



Wing R R, Missing, N - Fit/Remove 74,00




Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Door R L, Scratch(es), Acceptable 0,00

No pictures to display