



SKODA Fabia: 1ENK665

Vinnnumber:	TMBJK65J8D3100094	Versionname:	FABIA COMBI Ambition
First Registrationdate:	30/01/2013	Fiscalpower:	DPF 75PK
Expertise Mileage:	77771	Power Kw:	55
Bodytype:		Body color:	Blue
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3230
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	195/55/15/85 H Steel			
Summer tyres:	Fr.L.	Bridgestone: 2 mm	Fr.R.	Bridgestone: 2 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT	869,00
-------------------	--------

Door F R, Bump(s), PDR - Knock out without painting	63,00
---	-------



Bumper R, Bump(s) and scratch(es), Le - Replace and paint	0,00
---	------






Door F L, Bump(s), PDR - Knock out without painting 63,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 390,56



Wheel cover R R, Scratch(es), E - Replace 24,00



Door R L, Bump(s), Acceptable 0,00

No pictures to display

Wheel cover F L, Scratch(es), E - Replace 24,00



Tailgate, Bump(s), PDR - Knock out without painting 63,00



Wheel cover R L, Scratch(es), E - Replace 24,00



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 217,44



