



**VOLKSWAGEN Passat: 1EHK812**

Vinnumber:	<b>WVWZZZ3CZDE074709</b>	Versionname:	<b>PASSAT VAR Highline</b>
First Registrationdate:	<b>4/12/2012</b>	Fiscalpower:	<b>136PK</b>
Expertise Mileage:	<b>181149</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>163158 KM</b>	Parking lot:	<b>1606</b>
Maintenance:	<b>14-9-2017</b>		
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Seats electric F L	
GPS storage	<b>HD</b>	Seats F L ventilated	
GPS storage		Seats F R ventilated	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>235/45/17/97 V LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 6 mm</b>	Fr.R.	<b>Michelin: 6 mm</b>
	Re.L.	<b>Kleber: 8 mm</b>	Re.R.	<b>Kleber: 8 mm</b>

**Assistance equipment**

Repair kit	<b>No</b>	Compressor	<b>No</b>
------------	-----------	------------	-----------

Total cost ex VAT	<b>1129,52</b>
-------------------	----------------

Air vent R M, Broken, E - Replace	<b>156,00</b>
-----------------------------------	---------------



Rearview mirror housing L, Scratch(es), Acceptable	<b>0,00</b>
--	-------------



Mirror side blinker L, Broken, E - Replace 30,00



Door F R, Bump(s), PDR - Knock out without painting 122,40



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Door R L, Bump(s), Acceptable 0,00



Door R R, Bump(s), PDR - Knock out without painting 63,00



Alloy rim R L, Scratch(es), Acceptable 0,00



Bonnet, Bump(s), PDR - Knock out without painting 122,40



Floor covering F L, Worn, P - Check 0,00



Compressor, Missing, E - Replace 137,52



Windscreen, Repaired, P - Check 0,00



Door F L, Bump(s), Acceptable 0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door frame F L, Bump(s), Acceptable 0,00



Front bumper, Bump(s) and scratch(es), Acceptable 0,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00



Alloy rim F L, Scratch(es), Acceptable 0,00



Tailgate, Bump(s), Acceptable 0,00

