



## VOLKSWAGEN Golf: 1GIP901

|                                    |                          |              |                                 |
|------------------------------------|--------------------------|--------------|---------------------------------|
| Vinnnumber:                        | <b>WVWZZZAUZEP563112</b> | Versionname: | <b>GOLF VAR Trendline 105PK</b> |
| First Registrationdate:            | <b>18/02/2014</b>        | Fiscalpower: |                                 |
| Expertise Mileage:                 | <b>129584</b>            | Power Kw:    | <b>77</b>                       |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Grey</b>                     |
| Gearbox:                           | <b>MAN 5 VIT</b>         | Paint type:  | <b>Metalic</b>                  |
| Transmission:                      |                          | Rims summer: | <b>Steel</b>                    |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                       |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>3305</b>                     |
| Number of doors:                   | <b>5</b>                 |              |                                 |
| Number of seats:                   | <b>5</b>                 |              |                                 |
| Number head rests:                 | <b>5</b>                 |              |                                 |
| Rims summer:                       | <b>Steel</b>             |              |                                 |
| Category:                          | <b>Passenger Car</b>     |              |                                 |
| Oil level:                         | <b>OK</b>                |              |                                 |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                 |

## Options

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| Windows electric F             | Luggage cover                |
| Windows electric R             | Front parking sensors        |
| Cruise Control                 | Rear parking sensors         |
| Steering wheel multifunctional |                              |
| Radio multimedia               |                              |
| Type of headlighting           | <b>Headlighting Halogen</b>  |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining fabrics</b>        |
| Type of climate control        | <b>Autom climate control</b> |

## Limited Technical Inspection

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Idle position       | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Lighting            | <b>OK</b>  |
| Transmission        | <b>OK</b> | Wiperblades         | <b>OK</b>  |
| Handbrake           | <b>OK</b> |                     |            |

## Degree of wear

|               |                             |                          |       |                          |
|---------------|-----------------------------|--------------------------|-------|--------------------------|
|               | <b>195/65/15/91 T Steel</b> |                          |       |                          |
| Winter tyres: | Fr.L.                       | <b>Michelin: 6 mm</b>    | Fr.R. | <b>Michelin: 6 mm</b>    |
|               | Re.L.                       | <b>Continental: 5 mm</b> | Re.R. | <b>Continental: 5 mm</b> |

## Assistance equipment

|             |            |
|-------------|------------|
| Spare wheel | <b>Yes</b> |
|-------------|------------|

|                                      |        |
|--------------------------------------|--------|
| Total cost ex VAT                    | 512,20 |
| Bumper R, Scratch(es), Acceptable    | 0,00   |
| <i>No pictures to display</i>        |        |
| Windscreen, Scratch(es), E - Replace | 487,20 |



|                                 |       |
|---------------------------------|-------|
| Roof, Bump(s), Acceptable       | 0,00  |
| <i>No pictures to display</i>   |       |
| Seat cover F R, Dirty, Cleaning | 25,00 |

