



VOLKSWAGEN Transporter: 1HES726

Vinnumber:	WV1ZZZ7HZEH119572	Versionname:	TRANSP.1000 B/F2C LWB BMT Comf.114PK
First Registrationdate:	2/07/2014	Fiscalpower:	
Expertise Mileage:	153049	Power Kw:	84
Bodytype:	Transporter	Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2226
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Type of Tow bar	Tow bar fixed
Windows electric F		
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/65/16/107 T Steel			
Winter tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Semperit: 7 mm	Re.R.	Semperit: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1612,57
-------------------	----------------

Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	231,15
---	---------------



Bumper R, Bump(s), Smart repair	110,64
---------------------------------	---------------



Door F L, Bump(s), Acceptable 0,00

No pictures to display

Front bumper, Damaged, E - Replace 398,40



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 238,76



Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete) 217,56



Interior, Dirty, Cleaning 50,00



Trunk door R R, Bump(s) and scratch(es), It - Spot repair 115,56



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Sunblind L, Damaged, E - Replace 112,50





Rearview mirror R complete, Damaged, E - Replace

138,00

