



VOLVO XC60: 1GCS583

Vinnumber:	YV1DZ3150E2573164	Versionname:	XC60 D3 Kinetic Geartr.136PK Aut.
First Registrationdate:	2/01/2014	Fiscalpower:	
Expertise Mileage:	124328	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK		
Maintenance:	SERVICE IN 18973KM 3M		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric
GPS storage	HD	Panoramic roof
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	NOT OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	235/65/17/104 H LightMetal			
Winter tyres:	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	369,84
-------------------	--------

Alloy rim R R polished, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Ignition key, Missing, P - Check	0,00
----------------------------------	------



Headlight L, Not functioning (well), P - Check	0,00
--	------



Alloy rim F L polished, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete)	369,84
---	--------



Interior, No damage, Acceptable	0,00
---------------------------------	------



Door F L, Bump(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim R L polished, Scratch(es), Acceptable	0,00
---	------

No pictures to display