



VOLVO V40: 1DUP564			
Vinnnumber:	YV1MV8481D2005116	Versionname:	V40 D2 Base 115PK
First Registrationdate:	3/09/2012	Fiscalpower:	
Expertise Mileage:	95706	Power Kw:	84
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2116
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	205/55/16/94 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes

Total cost ex VAT	1016,83
Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80



Wing F R, Bump(s) and scratch(es), It - Spot repair	115,56
--	---------------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
--	---------------



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Armrest R M, Damaged, Smart repair 64,32



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00

