



## VOLKSWAGEN Touran: 1GCV654

Vinnnumber:	<b>WVGZZZ1TZEW042086</b>	Versionname:	<b>TOURAN Highline BMT</b>
First Registrationdate:	<b>3/01/2014</b>	Fiscalpower:	<b>Start/Stop 105PK</b>
Expertise Mileage:	<b>76977</b>	Power Kw:	<b>77</b>
Bodytype:		Body color:	<b>Dark Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>SERVICE IN 23600KM 307D</b>	Parking lot:	<b>2630</b>
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD		Luggage cover	
GPS storage	<b>HD</b>	Front parking sensors	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>Tow bar fixed</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

## Degree of wear

	<b>205/55/16/91 T LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 6 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>625,02</b>
Front bumper, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Door F R, Bump(s), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Alloy rim R L polished, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>



Wing F L, Bump(s), Le - Replace and paint 530,02



Interior, No damage, Acceptable 0,00

