



VOLVO XC60: 1GUM229

Vinnumber:	YV1DZ31A1E2616690	Versionname:	
First Registrationdate:	5/05/2014	Fiscalpower:	
Expertise Mileage:	153247	Power Kw:	100
Bodytype:	SUV	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3116
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
Windows electric F		Central consol F	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar removable
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

235/60/18/91 V LightMetal				
Winter tyres:	Fr.L.	Uniroyal: 3 mm	Fr.R.	Uniroyal: 3 mm
	Re.L.	Uniroyal: 3 mm	Re.R.	Uniroyal: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	974,16
-------------------	---------------

Roof, Stone chip(s), Acceptable	0,00
---------------------------------	-------------



Alloy rim F R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Rear window, Scratch(es), Acceptable	0,00
--------------------------------------	-------------



Windscreen, Repaired, Acceptable	0,00
----------------------------------	------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door panel R L, Tear, E - Replace	132,00
-----------------------------------	--------



Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Door panel F L, Damaged, E - Replace	132,00
--------------------------------------	--------



Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Headlight R, Crack, E - Replace	456,00
---------------------------------	--------

