



<b>SEAT Alhambra: 1CE0124</b>			
Vinnnumber:	<b>VSSZZZ7NZBV503048</b>	Versionname:	<b>ALHAMBRA Ecom.Reference DPF</b>
First Registrationdate:	<b>4/11/2011</b>	Fiscalpower:	<b>136PK</b>
Expertise Mileage:	<b>182390</b>	Power Kw:	<b>100</b>
Bodytype:	<b>MAN 6 VIT</b>	Body color:	<b>Beige</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4704</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

<b>Options</b>			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Type of headlighting	<b>Headlighting Halogen</b>	Type of Tow bar	<b>Tow bar fixed</b>
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

<b>Degree of wear</b>				
	<b>215/60/16/95 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Continental: 5 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Continental: 7 mm</b>	Re.R.	<b>Continental: 7 mm</b>

<b>Assistance equipment</b>	
Total cost ex VAT	2587,23
Wing F R, Bump(s), LI - Repair and paint (complete)	264,21



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	382,02
---	--------





Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,16



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Door R R, Scratch(es), LI - Repair and paint (complete) 382,02



Interior, Dirty, Cleaning 150,00




Door F L, Bad repair, Acceptable 0,00



Seat cover R, Hole, E - Replace 408,00



Rearview mirror housing R, Scratch(es), Smart repair 110,64



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 382,02

