



PEUGEOT 5008: 1EJR595			
Vinnnumber:	VF30ERHE8CS265178	Versionname:	5008 Allure FAP 150PK
First Registrationdate:	1/01/2013	Fiscalpower:	
Expertise Mileage:	72889	Power Kw:	110
Bodytype:	MPV	Body color	.
Gearbox:	MAN 6 VIT	Body color	Blue
Transmission:	Front	Paint type	Metalic
Fueltype:	Diesel	Rims summer	Aluminium
Battery functioning	Yes	Oil level	OK
Number of doors	5	Parking lot	2608
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options			
Radio CD		Panoramic roof	
GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Head-up Display			
Level control			

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
Winter tyres:	215/50/17/95 H LightMetal			
	Fr.L.	Kleber: 5 mm	Fr.R.	Kleber: 5 mm
	Re.L.	Kleber: 7 mm	Re.R.	Kleber: 7 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	771,60
Wing R R, Scratch(es), Acceptable	0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------

		Alloy rim R L, Scratch(es), Acceptable	0,00
		Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
		Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
		Door R R, Bump(s), PDR - Knock out without painting	63,00
		Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
		Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
			