



MERCEDES CLA: 1GFJ249

Vinnumber:	WDD1173031N060773	Versionname:	CLA BER 220 CDI 163PK Aut.
First Registrationdate:	23/01/2014	Fiscalpower:	
Expertise Mileage:	125061	Power Kw:	120
Bodytype:		Body color:	Purple
Gearbox:	Automatic	Paint type:	Metallic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1405
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/40/18/92 V LightMetal			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment

Repair kit	Yes	Runflat	Yes
------------	------------	---------	------------

Total cost ex VAT	1079,00
--------------------------	----------------

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
---	--------------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
---	--------------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
--	---------------



Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Damaged, E - Replace	487,20



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display