



AUDI A6: 1HPH006			
Vinnnumber:	WAUZZZ4G5EN179846	Versionname:	A6 BER 136PK
First Registrationdate:	4/09/2014	Fiscalpower:	
Expertise Mileage:	175766	Power Kw:	100
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1726
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
Summer tyres:	225/55/17/97 W LightMetal			
	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Goodyear: 7 mm	Re.R.	Goodyear: 7 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1629,04
Bonnet, Scratch(es), LI - Repair and paint (complete)			348,09



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------




Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Windscreen, Repaired, Acceptable	0,00
----------------------------------	------

No pictures to display

Tailgate, Chemical polution, LI - Repair and paint (complete)	362,02
---	--------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)	0,00
---	------



Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
--	--------



Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	264,21
---	--------

