



AUDI A4: 1GAQ904			
Vinnumber:	<b>WAUZZZ8K0EA081474</b>	Versionname:	<b>A4 BER TDie 136PK</b>
First Registrationdate:	<b>9/12/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>135066</b>	Power Kw:	<b>100</b>
Bodytype:	<b>Berline</b>	Body color:	<b>Dark Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3121</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options	
Radio CD	Central consol F
GPS storage	<b>DVD</b> Front parking sensors
GPS storage	Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

Degree of wear				
	<b>205/60/16/92 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Uniroyal: 6,5 mm</b>	Fr.R.	<b>Uniroyal: 6,5 mm</b>
	Re.L.	<b>Uniroyal: 7 mm</b>	Re.R.	<b>Uniroyal: 7 mm</b>

Assistance equipment			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			1169,26
Roof, Chemical polution, LI - Repair and paint (complete)			529,50



Alloy rim R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Covering interior front pillar L, Damaged, Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Chemical polution, LI - Repair and paint (complete)	349,68



Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------

