


BMW 1: 1FIL793

Vinnnumber:	WBA1C11040VU92676	Versionname:	1 BER HATCH 118d 143PK
First Registrationdate:	8/07/2013	Fiscalpower:	
Expertise Mileage:	197344	Power Kw:	105
Bodytype:	Hatchback	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3501
Maintenance:	27000KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 MS LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1029,18
-------------------	----------------

Wing R R, Bad repair, Acceptable	0,00
----------------------------------	-------------



Sill outer R, Scratch(es), LI - Repair and paint (complete)	310,50
---	---------------



Windscreen, Stone chip(s), Windscreen repair 58,80



Rear wiper blade, Damaged, E - Replace 20,00



Alloy rim R R, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R L, Bump(s), Acceptable 0,00

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Instrument panel cover, Crack, P - Check 0,00



Wing R R, Bump(s), Acceptable 0,00

No pictures to display

Foglight L, Damaged, E - Replace 138,00

