


AUDI A4: 1EHZ157

Vinnumber:	WAUZZZ8K3DA148504	Versionname:	A4 BER TDi 120PK
First Registrationdate:	10/12/2012	Fiscalpower:	
Expertise Mileage:	207826	Power Kw:	88
Bodytype:		Body color:	MET.
Gearbox:	MAN 6 VIT	Body color:	Grey
Transmission:	Front	Paint type:	Metalic
Fueltype:	Diesel	Rims summer:	Aluminium
Maintenance:	OK	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3302
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage	DVD	Rear parking sensors
GPS storage		
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/55/16/95 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT	570,46
Alloy rim R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Door panel R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Bumper grille, Broken, E - Replace	68,86



Door F R, Bump(s), PDR - Knock out without painting 63,00



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Tires, Not original part, P - Check 0,00



Internal Boot Lining R, Missing, E - Replace 15,00



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80

No pictures to display