



| AUDI A3: 1GS139 | | | |
|------------------------------------|--------------------------|--------------|-----------------------------|
| Vinnnumber: | WAUZZZ8V8EA174799 | Versionname: | A3 SB Ambiente 122PK |
| First Registrationdate: | 15/04/2014 | Fiscalpower: | |
| Expertise Mileage: | 44508 | Power Kw: | 90 |
| Bodytype: | | Body color: | Light Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2532 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

| Options | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Front parking sensors |
| Cruise Control | Rear parking sensors |
| Steering wheel multifunctional | |
| Seats F heated | |
| Type of headlighting | Headlighting Xenon |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining leather |
| Type of climate control | Autom climate control |

| Limited Technical Inspection | | | |
|------------------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

| Degree of wear | | | | |
|----------------|----------------------------------|--------------------------|-------|--------------------------|
| | 205/55/16/94 H LightMetal | | | |
| Winter tyres: | Fr.L. | Continental: 7 mm | Fr.R. | Continental: 7 mm |
| | Re.L. | Uniroyal: 6 mm | Re.R. | Uniroyal: 6 mm |

| Assistance equipment | | | |
|----------------------|------------|------|------------|
| Spare tyre compact | Yes | Jack | Yes |

| | |
|---|----------------|
| Total cost ex VAT | 1021,83 |
| Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete) | 301,68 |




| | |
|--|--------------|
| Alloy rim R R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|--------------|



| | |
|-----------------------------------|-------------|
| Wing R R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|-------------|

No pictures to display

Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display