



AUDI A6: 1BVY200

Vinnumber:	WAUZZ4G3EN185287	Versionname:	D
First Registrationdate:	28/08/2014	Fiscalpower:	
Expertise Mileage:	96817	Power Kw:	140
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	4230
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	SD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/55/17/101 H LightMetal			
Winter tyres:	Fr.L.	Dunlop: 5 mm	Fr.R.	Dunlop: 5 mm
	Re.L.	Pirelli: 3 mm	Re.R.	Pirelli: 3 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT	3139,93
-------------------	----------------

Maintenance book, Missing, E - Replace	0,00
--	-------------




Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	302,16
---	---------------



Maintenance, Maintenance, Execute 0,00

No pictures to display
Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Rearview mirror L complete, Broken, E - Replace 192,00



Interior, Dirty, Cleaning 340 150,00



Certificate Of Conformity, Missing, E - Replace 150,00



Roof, Scratch(es), 67 - Polish 55,19



Door R R, Scratch(es), 67 - Polish 55,19



Tailgate, Scratch(es), LI - Repair and paint (complete) 362,02



Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 526,02



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)

302,16



Rearview mirror glass L, Broken, E - Replace

21,60



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Bonnet, Chemical pollution, 67 - Polish

55,19



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)

417,84



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Ignition key, Missing, E - Replace

150,00

