



|                         |                          |              |  |
|-------------------------|--------------------------|--------------|--|
| <b>BMW 5: 1ENP370</b>   |                          |              |  |
| Vinnumber:              | <b>WBAXB31060DW53771</b> | Versionname: | <b>5 TOURING 525dAS St/St 211PK Aut.</b> |
| First Registrationdate: | <b>31/01/2013</b>        | Fiscalpower: |  |
| Expertise Mileage:      | <b>101700</b>            | Power Kw:    | <b>155</b>                               |
| Bodytype:               | <b>Break</b>             | Body color:  | <b>Black</b>                             |
| Gearbox:                | <b>Automatic</b>         | Paint type:  | <b>Metalic</b>                           |
| Transmission:           |                          | Rims summer: | <b>Aluminium</b>                         |
| Fueltype:               | <b>Diesel</b>            | Oil level:   | <b>OK</b>                                |
| Battery functioning:    | <b>Yes</b>               | Parking lot: | <b>2709</b>                              |
| Number of doors:        | <b>5</b>                 |              |  |
| Number of seats:        | <b>5</b>                 |              |  |
| Number head rests:      | <b>5</b>                 |              |  |
| Rims summer:            | <b>Aluminium</b>         |              |  |
| Category:               | <b>Passenger Car</b>     |              |  |
| Oil level:              | <b>OK</b>                |              |  |

|                                |                              |                       |                      |
|--------------------------------|------------------------------|-----------------------|----------------------|
| <b>Options</b>                 |                              |                       |                      |
| Radio CD                       |                              | Seats electric F L    |                      |
| Windows electric F             |                              | Seats electric F R    |                      |
| Windows electric R             |                              | Sun Roof electric     |                      |
| Cruise Control                 |                              | Panoramic roof        |                      |
| Steering wheel multifunctional |                              | Luggage cover         |                      |
| Seats F heated                 |                              | Front parking sensors |                      |
| Radio multimedia               |                              | Rear parking sensors  |                      |
| Type of headlighting           | <b>Headlighting Xenon</b>    | Type of Tow bar       | <b>Tow bar fixed</b> |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |                      |
| Type of Lining                 | <b>Lining leather</b>        |                       |                      |
| Type of climate control        | <b>Autom climate control</b> |                       |                      |

|                                     |           |                     |            |
|-------------------------------------|-----------|---------------------|------------|
| <b>Limited Technical Inspection</b> |           |                     |            |
| Airco functioning                   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile                  | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Idle position                       | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Engine startingtime                 | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Exhaust gass                        | <b>OK</b> | Lighting            | <b>OK</b>  |
| Transmission                        | <b>OK</b> | Wiperblades         | <b>OK</b>  |
| Handbrake                           | <b>OK</b> |                     |            |

|                       |                                  |                          |       |                          |
|-----------------------|----------------------------------|--------------------------|-------|--------------------------|
| <b>Degree of wear</b> |                                  |                          |       |                          |
|                       | <b>245/45/18/96 V LightMetal</b> |                          |       |                          |
| Winter tyres:         | Fr.L.                            | <b>Bridgestone: 6 mm</b> | Fr.R. | <b>Bridgestone: 6 mm</b> |
|                       | Re.L.                            | <b>Bridgestone: 3 mm</b> | Re.R. | <b>Bridgestone: 3 mm</b> |

|  |         |               |
|--|---------|---------------|
| <b>Assistance equipment</b>                                    |         |               |
|  | Runflat | <b>Yes</b>    |
| <b>Total cost ex VAT</b>                                       |         | <b>603,32</b> |
| <b>Bumper R, Scratch(es), LI - Repair and paint (complete)</b> |         | <b>254,16</b> |



|  |  |               |
|--|--|---------------|
| <b>Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)</b> |  | <b>254,16</b> |
|--|--|---------------|



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00

