



<b>BMW X5: JD6290</b>			
Vinnumber:	<b>WBAKS410400H63311</b>	Versionname:	<b>3.0 XDRIVE30D 4WD AUTO</b>
First Registrationdate:	<b>1/03/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>45183</b>	Power Kw:	<b>190</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2727</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

<b>Options</b>	
Radio CD	Seats electric F L
Windows electric F	Seats electric F R
Windows electric R	Sun Roof electric
Cruise Control	Panoramic roof
Steering wheel multifunctional	Central consol F
Seats F heated	Luggage cover
Radio multimedia	Front parking sensors
Type of headlighting	Rear parking sensors
Type of GPS	<b>Headlighting Xenon</b>
Type of Lining	<b>GPS big screen color</b>
Type of climate control	<b>Lining leather</b>
	<b>Autom climate control</b>

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

<b>Degree of wear</b>				
Summer tyres:	<b>315/35/20/110 V LightMetal</b>			
	Fr.L.	<b>Pirelli: 7 mm</b>	Fr.R.	<b>Pirelli: 7 mm</b>
	Re.L.	<b>Pirelli: 6 mm</b>	Re.R.	<b>Pirelli: 6 mm</b>

<b>Assistance equipment</b>	
Runflat	<b>Yes</b>
Total cost ex VAT	<b>2054,03</b>
Door F L, Scratch(es), Acceptable	<b>0,00</b>



Door F R, Scratch(es), LI - Repair and paint (complete)	<b>382,02</b>
---	---------------





Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Scratch(es), LI - Repair and paint (complete) 382,02



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 382,02



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Broken, LI - Repair and paint (complete) 115,56



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Floor covering F R, Damaged, Smart repair 64,32



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Scratch(es), LI - Repair and paint (complete) 348,09

