




CITROËN Berlingo: TZ7671	
Vinnumber:	VF77B9HN0CN544483
First Registrationdate:	6/02/2013
Expertise Mileage:	192833
Bodytype:	Transporter
Gearbox:	MAN 5 VIT
Transmission:	Front
Fueltype:	Diesel
Battery functioning	Yes
Number of doors	5
Number of seats	3
Number head rests	3
Rims summer	Steel
Category	Light Commercial Vehicle
Oil level	OK
Registration Certificate Car (BE)	Yes
Versionname:	BERLINGO B/F Kort Fresh
Fiscalpower:	75PK
Power Kw:	55
Body color	White
Paint type	Opaque
Rims summer	Steel
Oil level	OK
Parking lot	1620

Options	
Radio CD	
Windows electric F	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
Winter tyres:	195/65/15/91 T Steel			
	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment	
Spare wheel	Yes Jack Yes
Total cost ex VAT	1024,01
Wing R R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Bodywork, Not original part, Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Bump(s), LI - Repair and paint (complete)	217,56



Front bumper, Scratch(es), Smart repair	110,64
---	---------------



Wheel covers (all), Missing, E - Replace 96,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display


Windscreen, Stone chip(s), Windscreen repair 58,80



Wing R L, Bump(s) and scratch(es), It - Spot repair 115,56



Roof, Bump(s), LI - Repair and paint (complete) 361,13



Backrest cover F L, Hole, Smart repair 64,32

