






FORD S Max: 1GGX575			
Vinnnumber:	WF0SXXGBWSEL15462	Versionname:	S-MAX Titanium Style DPF
First Registrationdate:	5/02/2014	Fiscalpower:	136PK
Expertise Mileage:	226288	Power Kw:	100
Bodytype:	MPV	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3231
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Panoramic roof
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining leather
Type of climate control:	Autom climate control

Limited Technical Inspection			
Airco functioning:	OK	Battery functioning:	Yes
Tires wear profile:	OK	Sound engine:	OK
Idle position:	OK	Clutch test:	OK
Engine startingtime:	OK	Wiper fluid level:	OK
Exhaust gass:	OK	Lighting:	OK
Transmission:	OK	Wiperblades:	OK
Handbrake:	OK		

Degree of wear				
	225/50/17/94 H LightMetal			
Winter tyres:	Fr.L.	Semperit: 4 mm	Fr.R.	Semperit: 4 mm
	Re.L.	Semperit: 5 mm	Re.R.	Semperit: 5 mm

Assistance equipment			
Repair kit:	Yes	Compressor:	Yes
Total cost ex VAT		607,02	
Tailgate, Scratch(es), LI - Repair and paint (complete)		362,02	

			
Wing R R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Front bumper, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Ignition key, Missing, E - Replace			150,00
<i>No pictures to display</i>			
Door R L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			

no pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Door R R, Bump(s), Acceptable

0,00

No pictures to display