


BMW 5: 1EZG361

Vinnumber:	WBAMX11080C978811	Versionname:	5 TOURING 520d
First Registrationdate:	26/04/2013	Fiscalpower:	Start/Stop 163PK
Expertise Mileage:	130891	Power Kw:	120
Bodytype:	Break	Body color:	Beige
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2832
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control
Level control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/55/17/97 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 7 mm	Fr.R.	Goodyear: 7 mm
	Re.L.	Goodyear: 7 mm	Re.R.	Goodyear: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1188,96
-------------------	----------------

Bonnet, Bump(s) and scratch(es), Acceptable	0,00
---	-------------

No pictures to display


Alloy rim F L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Front bumper, Crack, Le - Replace and paint	862,80
---	---------------



Rear window, Scratch(es), E - Replace	0,00
---------------------------------------	-------------



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 326,16

