


**FORD Focus: 1FIH221**

Vinnumber:	<b>WF0LXXGCBLDR07916</b>	Versionname:	<b>FOCUS CLIP. ECONetic Trend 88g 105PK</b>
First Registrationdate:	<b>5/07/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>112793</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Break</b>	Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2332</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>HD</b>	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>205/55/16/91 MS Steel</b>			
Winter tyres:	Fr.L.	<b>Bridgestone: 4 mm</b>	Fr.R.	<b>Bridgestone: 4 mm</b>
	Re.L.	<b>Bridgestone: 4 mm</b>	Re.R.	<b>Bridgestone: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	1484,19
-------------------	---------

Seat cover F L, Stain, Forfeit	12,00
--------------------------------	-------



Door F L, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Rear window, Scratch(es), Acceptable	0,00
--------------------------------------	------



Door R L, Bump(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Front bumper, Crack, Le - Replace and paint	735,00
---	--------



Door R R, Bump(s), E - Replace	0,00
--------------------------------	------

*No pictures to display*

Roof, Scratch(es), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Bumper trim R, Scratch(es), Smart repair	110,64
--	--------



Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20
---	--------

